

Testing results for 2022/2023

Rotary Clothes Dryers



Each year EECA conducts laboratory testing to make sure manufacturers' and importers' products meet the requirements of the [Energy Efficiency \(Energy Using Products\) Regulations 2002](#).

This year, ten models of rotary clothes dryers were tested by an accredited laboratory to check if they pass or fail Mandatory Energy Performance Label (MEPL) requirements. The testing results are presented in the table below.

Brand	Model	Record ID	Pass/Fail
Robinhood	RHVD45UDW	126624	Pass
Electrolux	EDV605H3WB	133696	Pass
Haier	HDV40A1	140950	Pass*
Midea	DMDV70	108897	Pass
Beko	BDP810W	119781	Pass*
Kogan	KA6VDRYERA	115346	Pass*
Seiki	SC-70AU6DR	110861	Pass
Bosch	WTR85T00AU	124846	Pass*
Parmco	DR7WHP	149469	Pass
F&P	DE7060G2	147407	Pass

*Measured energy consumption exceeds energy consumption on the label. This does not affect the validity of the energy rating label.